

Firmware Changelog

Version 1.8.2 (Latest Version)

- Improved USB recovery in case of fault event (e.g. ESD fault)
- Improved DC motor output linearity
- Improved closed-loop control modes
- Improved I2C speeds
- Minor bug fixes

[Download REV Hub Firmware Version 1.8.2](#)

Version 1.7.2

- Fixes a bug where encoder counts would occasionally reset.

[Download REV Hub Firmware Version 1.7.2](#)

Version 1.7.0

- Fixes a bug where some I2C sensors can lock up the bus causing other additional performance issues.
- Added new status LED blink code:
 - Blinking orange indicates the Hub is only powered over USB. In other words, turn on your main power switch!
- Other minor performance tweaks.

[Download REV Hub Firmware Version 1.7.0](#)

Version 1.6.0

- Original Release

[Download REV Hub Firmware Version 1.6.0](#)